

WP-15

WATERLESS CLEANER

Technical Data Sheet

DESCRIPTION:

A Waterless Tacking Liquid.
A cleaner used for tacking rags during the refinish application of oil modified urethane finishes.

ADVANTAGES:

- Easy to use
- Excellent for dust removal
- Compatible with OMU finishes
- Removes solvent and paste waxes
- Uniformly cleans surfaces

PACKAGING:

Product is available in 1 and 5-gallon containers.

COVERAGE:

400 - 500 square feet per gallon

ASSOCIATED PRODUCTS:

- **WP-17** Neutral cleaner

RELATED EQUIPMENT:

- Single disc floor machine, low speed (150 - 200 rpm). 17 - 20-inch diameter #100 or #120 grit Abrasive disc screens.
- 24 inch push broom for sweeping and tacking
- Terry cloth towels for use as tack rags
- Putty knife or scraper

CAUTION: COMBUSTIBLE LIQUID

- 1) Keep away from heat and flames, **No smoking**.
- 2) No non-explosion proof motors AC or DC when wet screening. Arcing brushes cause sparks.
- 3) No automatic scrubbers or wet vacuums.
- 4) Avoid storage or use in hot areas >95F.
- 5) Avoid prolonged breathing of vapors or mist. Open doors and windows to ensure fresh air entry during application and drying. If necessary wear respiratory equipment (NIOSH/ MSHA TC-23C or equivalent).
- 6) Avoid skin contact, eye contact, or clothes contamination.

GENERAL PROPERTIES:

		ASTM
Color	1 - 2 water white	D1544
Viscosity	A5 - A4	D1545
Weight/Gallon	6.3 - 6.4 Lbs.	D1475
Solids	0%	D1644
Flash Point	104°F	D56

DIRECTIONS:

- 1) Remove tape, gum, and debris from the floor.
- 2) Clean the floor of dirt, dust mop treatments, body oils, etc with **WP-17 neutral cleaner**.

Dry screening

- 1) After the floor has dried, screen with #100 grit screens.
- 2) After screening, tack the floor with **WP-15 Waterless Cleaner** to remove the dust.
- 3) Continue tacking until the rag is free of dust.
- 4) Allow the floor to dry. Now the floor is ready for a solvent-based finish.

Wet screening

Low dust generated.

- 1) Mop a ~ 100 sq. ft area with **WP-15 Waterless Cleaner**.
- 2) With an **EXPLOSION PROOF FLOOR MACHINE** and #100 grit screens, screen the area.
- 3) Continue steps 1 - 2 until the entire floor is completed.
- 4) Tack the floor with **WP-15 Waterless Cleaner** until the rag is free of dust.
- 5) Allow the floor to dry.
- 6) Check the floor for unscreened patches. If okay the floor is ready for a solvent based finish.

FIRST AID:

- 1) Skin contact wash with soap and water.
- 2) Eye contact flush with water for 15 minutes and get medical attention.
- 3) If swallowed do not induce vomiting, get medical attention immediately.
- 4) If experience watering eyes, headaches, dizziness, nose or throat irritation; increase the flow of fresh air, or leave the area.

NOTICE:

1. **SPONTANEOUS COMBUSTION:** Dust created from screening oil based finishes and rags soaked with oil and dust can auto-ignite causing a fire. DO NOT store or throw away the dust and oil soaked rags into a closed vacuum or trash can. Immerse the dust in water and open the rags to air dry before discarding the waste. High temperatures, high humidity and freshly applied seal increase the potential for a fire.
2. Long term overexposure to solvents have been associated with permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling the contents may be harmful or fatal.
3. In case of a spill absorb with inerts like sawdust or "oil dry" and wipe. Dispose in accordance with local regulations.
4. Empty containers may contain product residue, including flammable or explosive vapors. Do not cut, puncture, or weld on or near container.

DISPOSAL:

All label warnings must be observed until the container has been commercially cleaned, reconditioned, or disposed of in accordance with local government regulations.

Refer to Material Safety Data Sheet for further safety and handling information.

**For Emergency Medical Information call
1-888-345-5732**

KEEP OUT OF REACH OF CHILDREN.

© Copyright 2007 Valspar Corporation. All rights reserved.

TDS-WP15 | Rev 03/15/07 ly